


Izrada dodatnog priključka




Obilježavanje
sredine visine
dodatnog priključka




Odabir krunskog
svrdla i . . .



. . . postavljanje
na ručnu el.
bušilicu




Bušenje rupice $\phi 6$
mm i . . .



. . . otvora za ulaznu
brtvu



Vađenje izreza



Čišćenje ruba



Mazanje ruba . . .



i ulazne brtve




Postavljanje
ulazne brtve




Mazanje ruba
ulazne brtve i . . .



. . . PVC cijevi



Priključenje PVC
cijevi



Pravilna izvedba
dodatnog
priključka



Za PVC rebrastu cijev
- muški prelazni komad



Izvedba dodatnog priključka za PE-rebrastu cijev
s muškim prelaznim komadom



Za PVC rebrasta cev
- PE prehodni kos